



F-14 WIRING SYSTEM AWARENESS

PREVENTING WIRING SYSTEM FAILURE SAVES TIME, MONEY...

AND LIVES!



Harness chafing braided hydraulic line.



Harness chafing on structure.



High voltage power cable chafing on AWG-9 power supply.



Coax lying on hydraulic line.



Damaged wiring/exposed conductors.

ALWAYS MAINTAIN THE CORRECT WIRING SYSTEM CONFIGURATION !